Menlo Park Notebook #80 [N-79-06-12]

This notebook covers the period June 1879-September 1880. The entries are by Edison, Charles Batchelor, John Kruesi, and Francis Upton. Most of the material relates to electric light or telephone experiments. The electric light material includes notes, calculations, and drawings of generators; drawings of filaments, bulbs, and sockets; and notes on equipping the Menlo Park lamp factory. The telephone material includes notes and drawings relating to telephones, central exchange systems, and chalk experiments. There are also notes on ore separation and notes and drawings of the electric railroad. The book contains 282 numbered pages.

Blank pages not filmed: 60-63, 94-95, 114-117, 134-135, 188-189, 198-199, 206-243, 246-247, 250-255, 258-261, 266-269, 272-273, 276-279.

Missing page numbers: 165-166.

Do so

Experiments on Chemical?

Ice pheone June 12 1879.

Connections

Tuesday end.

8 H.P.

500 turns 15 ft 2500 ft per hour

gas 70 c ft per M

= 175.

8 H.P. 500

62

No 80

LIBRARY OF THE

BOARD OF PATENT CONTROL,

120 BROADWAY, NEW YORK.

, 189 .

Experiments on Chemical Telephone June 12 1879.

TAE

Connections

Transmitting end.



June 12 1914 Gal 3

When A is in only & X is out it is exceedingly loud, when X is in it reduces it to ¼ of the volume —

When both A+B are in the cutting out of X does not materially alter the volume of sound

---

I have just found a way of large dimensions which is that sometimes when B is cut in [illegible] sound can be heard in A at other times [illegible] no difference, this phenomenon must be due to polarization.

June 12 1879 TAE

I find that with 2 chalks
the current that will
polarize one will not
always sufficiently
polarize the other hence
one chalk will be loud
& the other low, If the
battery is increased so
as to overpolarize both
the Chalks may have
the pressure increased
on one & decreased on
the other & the will
bring them OK so
that when
one is taken out of ckt
the other will go low
owing to increase in

June 12 1879 Tap

Strength of polarizing Current ~~too~~ when this very low the insertion of the other cheeks makes it loud again as it weakens the polarization Current, On the other hand when one is out & the other is over polarized & low increasing the ~~less~~ pressure on the spring so that it will do as before & loudness will be nearly restored

June 12 1874 TAE

Just tried experiment of putting induction Coil in line (10) its primary coil of 40 ohms resistance & putting the chalk in a local formed of the secondary of 500 ohms & worked quite loud - & inserted the other chalk right in the line & it did not make any difference but putting in the induction Coil of 40

June 22 1879 Tag

regular telephone ||

X lowered & greatly
improved by putting
Carbon Transmitter in
line with 4 Co Cells
Carbon battery
placing primary of
induction in ~~Coil~~
line & putting Chalk
in receiving Speaking
that you can ocasionally
hear it with 100 ohms
in circuit with 4 small
Carbon Cells in line
with 12 ohms it is fair

June 12 1899 TAE

We not use 1 cell carbon in Line & found the transmitter & conduit to see effect. It works (one cell) but 12 ohm rheostat makes it Cosy —

We now wind 4 layers of 23 wire on the outside of the induction Coil forming a tertiary coil in the circuit of the wire we put the choke & following Gaither & Lincoln coil & find that it comes strong & loud in fact as loud as the old way when both induction coils in also

June 2 1879 Tel 13

That 12,500 ohms may be inserted in the line & it is still receivable over a fair day's work. Then would 6 layers of No 3 wire on a [illegible] Bergmann Coil for a Telephone & find it as loud, this ex to Resistance over that which is [illegible] by a 23 wire from the Chalk ckt shortened the induction from the Coil to the talking — The greater the resistance that can be put in this Telephone & still work

June 21 1894 Thurs

land the better it
will be when harvesting
for the other way —
By this means we make
each Chalk reservoir
entirely independent
of Everything else & have
a perfectly Constant
Calcareous effect
Chalk we can use a
Chloride of Calcium &
to salage the Chalk
this will prove
Last 2 years

We propose to do
away with the cumbersome
system through
the Board in
little Multiple Factory =

New Business

Carb Barium 1st class
"
" Gypsum -
Chalk Hyd Sulp Magnesia "
but not proceed -

Salmon Ko 0-41/2 class Mfg

Slaked lime. June 12 1879 Tor
Too rough. unsuitable -
grind for Calcium - ng

Common Salt - good
st. clear
Hg + $CaCO_3$ -

Platinum - We found that
it want a very slight
Current to polarize the
Salt Cutter if Battery is
too strong it is too
irregular scarcely readable
which is with shunt polarizing
cell down to 1 ohm we get
it loud & clear -
Lake & shunt & it low &
very irregular.

2 Hrs. probable that Every Solution will require a different polarizing Current Chalk seems to require 3/4 or 1/2 Daniel Salt 1/20 of a Daniel roughly speaking -

Common Salt. Best Better than chalk; melting point 814° C - it will work very near as Low without polarization -

Sulphate Baryta - grams 2.4942 -

Fust Class - negative

just 1 coil Daniel for polarization = ~~2~~ 2 ~~of~~ 1 cut off 1st time ~~but~~ full loudness without coating — ~~coat~~ afterward ~~coat~~ coat it & for 20 to 30 seconds 10 minutes too great polarization because it was too hot & conductivity about two thousand ohms —

26

27



28

29



April 15 - 1879 pm

Final test of Chalk June 27, 1879.

Chalk Lithia - chalk soft

Chalk - Ferrocyanide Potassium good ½ hardness of Eng. Chalk - perhaps 2/3 hardness

Chalk Tartaric acid just the slightest faint cast round

32

Chalk. Pulphate of Zinc. 5 3
Irregular Low. July 5 1879

Chalk Iretate of aluminum
Low

2 oz Chalk
1/4 oz caustic K O
Cannot see any difference
between the regular Caustic Na O
or K O. Lond and clear

Chalk Iodide of Potassium
Very low

Chalk Grape sugar
very very low

Chalk permanganate of K
very very low

Chalk Sulphate of Cu
very very low

Chalk Three drops Ferric Chloride
10 " Chloride of Calcium
very ~~very~~ low

Chalk Nitrate of lime
pretty low

Chalk H_2O 15 drops of
acetic acid.
N.J.
Forms acetate of Ca



Chalk Bichromate of K 37
fair, not very bad.

Chalk H_2O ~~Rest~~ and 4 drops of Ferric Chloride
M. G. June 15 1894

Chalk 1 1/2 g, and 1/2 oz
Neutral Sulphate of Soda
As good as regular
solution saved

Chalk Nitrate of Zn
very very very thin

Chalk Tartrate of Soda
very low

Chalk 1 oz Caustic Soda
20 drops Silicate of Soda

Put in 20 [illegible] regular
2/3 oz bird [illegible]

Chalk [illegible] extremely [illegible]

Chalk Phenolic acid
very very [illegible]

Chalk very weak solution
caustic soda

Cure 1/4 bird regular

Chalk wet for 1 1/2 hours
laid out for 8 hours
4/5 of regular.

40

July 4 1879

Phosphate of Lime 1/4 oz saturated
Chalk 2 oz
Moderately wet

50/200 .40 Daniells

.05 Daniells constant on line

Very wet .35 Daniells

.07 Daniells constant on line

not quite as loud as regular

Regular soaked 2½ minutes
.4 Daniells ½ oz quinine
.075 constant
very loud

+2

Nothing July 4. new [illegible] on a [illegible] 43
regular, baked hard but
when dry fair

Wet fair but irregular
made the shuttle jump.
scraping made it harder

Soft regular
Putty fair

Old regular which was used
yesterday smooth fitted well
Stuck in apparently two hard
Hand as shown outside soft
inside.

Edison telephone July 7th 1899
5 AM.

At 2 pm July 4th Edison and Batcheller were experimenting on chalks and put away on shelf 2 chalks for test one was

No 1 — 2 oz Chalk
¼ fluid oz Caustic Soda
Hard pressed

No 2 was — 2 oz Chalk
¼ oz Phosphate Soda

At this time they both looked alike

July 7th 1899 5 am
the No 1 was almost played out
the No 2 was very good not quite so loud as we have heair but loud enough for regular work
No 1 was wet
No 2 was put away again on shelf.

See page 49

46

Edison Telephone
July 7 1879
Charge Battery 5 AM
2 oz Chalk
1/4 oz Caustic worked good on July 4 2 p.m.

Soaked 2 days in a 10 pc. Solution of Caustic Soda
Left out tile now to dry.
July 7 5 AM Worked exceedingly loud and clear.
Testing her was will 340 tertiary

July 9th 1 AM 1879
1/4 loudness and uneven, much lower than No 2. Page 49

July 10th 4 AM
1/2 loudness

July 16 2 AM
Edison just hears it at daylight
No effervescence

from page 45 Characteristics

No 1 by wetting came up to about $\frac{2}{3}$ th original loudness.

July 9 1AM

No 2 came as on 7th this is simply wonderful

put away again on shelf

No 1

same loudness as No 2

put away again on shelf

July 10 - 4AM.

No 2 about $\frac{1}{2}$ loudness of yesterday

No 1 about $\frac{1}{7}$ loudness have to put your ear down to it

55

Edison telephone July 7 1899 37

5 A.M.

Chattanooga Tenn

2 chalks wet with ¼ Phosphate Soda were made on July 3 and have been out on the shelf ever since; when put in telephone worked well and pretty [illegible] loud voice

I left one shelf after trying the other was left on shelf to soak in solution of Phosphate Soda but crumbled down in the solution

July 9 1899 1 a.m. The one left was fully talking good without any time being wet

Put on the shelf again to wait

July 10 4 a.m.

Shell talks good but pretty low

52

Edison's telephone July 7th 1879

5 AM
Took a receiver
Made a regular chalk July 3
at 2 p.m. and put it to soak
in 10% solution of Caustic Soda
with top out
at 5 AM July 7 it was tried and
worked half loudness

July 9 1 AM tried again
very low Edison could hear
it at all unless he put his
ear right down on the drum.
then it is quite loud to him

July 10 4 AM
about same

5-4

July 15th 2 AM frompage [illegible]

1/4 to 1/5 loudness 49

when he talks 3 inch away we can hear it a foot away

Edison wipes the efflorescence from No 1 before using

1 1/2

No 2 about 1/6 loudness

Edison hears it 2 inch away — No efflorescence

Inertia telephone was here put in and it did not work quite so well as our ordinary transmitter but when Edison wore out No 2 with water it worked a little better and afterwards came out nice and loud

J-C

July 16 1879
2 AM

Chas Batchelor

Quentra telephone this telephone works excellent and does not require adjustment even when you shout in the diaphragm

58

July 17 1874 fcb

59



1 hp.
3 sq ft 1 inch steam pipe

140 sqft	150
70	300
35	600
17 1/2	1200
8 1/2	2400
4 1/4	4800

64

65



July 25
1877
Tues.

120.

Separation of silica from Gold & Copper by dissolving the gold...

May 1880

60

13

3 9.

33

.6

.1.

13

26

S

12½

100.

68

266

190

124 266
124 67
1362
1596
1782
342
228
542

124

1389
·81
1389
111
·81
1259

30,19

36 -

55 55

35

226.5

228564
65304
55.16
12 12
176392
88196
1058 92

88.



125.19

69

$$9255 : 005 :: 01740 : 94$$

$$X : 005 :: 01740 : 94$$

$$94 : 01740 :: 005 : X$$

$$94 : 01740 :: 005 : 1740$$

$$9255 \overline{)94} \quad 1740$$

$$1740 \quad 94 \quad 1740$$

$$94 \quad 1740$$

$$18.44 \quad 18.44$$

$$220.00 \quad 18$$

$$94$$

$$1740$$

$$94$$

$$94$$

$$1740$$

$$94$$

$$94$$

$$94

Telephone Connections
Oct 31 1919



74



76

77



Oct. 31 1871

78

79



Dec 28th 79.

Boring No 2

Intake Diameter of drum wire 9.05

Diameter of piece 9.28

Diameter of bore No 2 9.65









Dec 24. 1879
Tar

Dec 29 1879
Tar



Dec 29 1899





Dec 24 1871

Log making machine April 20th 1880



92

Corp. making machine Apl 30 1850 93




96
97
Jany 5 1880
Jany 5 1880
Tue
Tue
Lecture

98

No 1 Good

" 2 NG

" 3 very good & durable

" 4 a little better than

" 5 Brass wire brush result in this position same as under No 3.

" 6 N.G. Brass brushes a little scratch but very little effect at all. The work was thrown on the after washing

Experiments 99

on Rubber Tile Sept 5th 1880

J. Prince

TRP

We found by turning the brush out at right angles & to commutator the sparks disappeared & which led to the following experiments



100

Very very nice brushes. Fast
Making all over the
Board clear
near as good as 5 3
& 5 wears off fast all work
shows on this mach.
8 brushes
very good copper

9 Narrow brush same 5
Little sparks but no current
mach

10 same brushes
Does more work
Sparks on the 5 has much
equally as good than 3 & 5

11 same brushes as in 7 (wide)

12 same brushes as in 8.9 10 but
contrary angle very good Does more
work in 1/2 time other mach without
sparking













OK very good standard

Current direction
to the wire only
390

102

14



NG

Feby 6 1880

for

103

1

34

16

410

1450

3


104
Fabry & 1550
TEM
101
Fabry & 1550
TEM



Feb 8 1880
TAE

Feb. 10th 1880 107

Experimental Armature
with sheet brass post on end.
spiral ◎ 80 ft. No 32 wire

Very bad.

TAE

March 9th 1880 109

Temperature at the start 19°

Number of Lamps on
machine No 6 = 75

65°

T.C.



Table 8 oz. Tray of Cake
[illegible] must be accompanied
[illegible] with 30 Cts. Postage
of Doctrine matter.

For [illegible] Chairs Table 1¾ oz 8
2 Dishes

Sept 3d 1882

Model



See page 99
This book

May 6 1880 Fair

Idea, little electromotor cause shaft
with arm on a track on pipe track
being Compared at ends



120

at Weight Cutomers,

121



May 6 1880

Porter can make us a pair of small Engines to work two magnets, Each with Cranks & The Current from one Bunsen Battery going all the Coils in one Circuit of Wire, & the other to a spare, We have a Lever Connected with the Governor so that any required speed may be obtained with the Engine. Hence we can regulate the Clock or Chronometer or Chronometers driven by Varying the speed of the Engine,









128

156

150



78

60) 100 (166
60
40
36

15) 166 (11
15
1



36

78

129

156

736 15-1680

15
20
3.00

60

7) 16 (86
56
4

60 H.P
8
48

14

1160
55
48

1 H.P 3

130



Jan. 20 1880
Mr. Upton's calculation

4/56
.14 ohms

39 commutators
2
78 cuts
2
156
150

75 commutators.

131

600
750
800

7 by 15 T&C
T&C

600 120 Volts
1200 120 Volts



63

132

35 light

~~to~~ 1/4 light

70 2

35

7

146

2000
200 2000000
200000

2000

133

3. Shine

6 to 1

6 .1

1 .1

1

18

125 22,000
250
2200

125 2

58 22,500
125
7100 FT

125
250
250
58 14500.00 #7620
232
1.30 58 #7620
466
350
120
670



75'

24







142

143



Feby 20 1880

144

Circumference 10 ft 1/4"




March 20
1880
Tab
Rubber


H.P.G.
Switch
Machine
Resistance boxes in series
H.P.G.
March 25
1880
Heavy wire



Circuit D 1860
T.C.E




H. R. 4
Switch
Machine
Boxes
H. R. 4.
Large wire
1/1

April 13- 1880



April 6 1880
Jig



April 6 1880
Jig




avril 16-80
avril 16 1880

April 16. 80

TAE



April 16 1880






166
167
1000
112
9
12 1008 = 84 1000
48
18
72
84
84
250 1510 6
1500
6 I
18 II
12 III
9 IIII
112



March 12 1880

March 12th 1880






Iron plate
Wood
Iron



40 ft
4 feet

Hemispherical same as in glass house



Repair Glass Blowers

1 man to blow in mould,
4 heaters —
2 pullers - large
2 pullers, small —
4 = Sealers to inside small
4 Sealers for large, ready for vac
2 to Blow in mould —
2 pinchers after vac

Bench
· Loop cutting Machine, + place for man +
· Shelves for wood, unfinished + finished

1 Bench for furnaces

Bench Saw for working wood —

Bench Clamping machine —

~~Gas~~
Bench Rack for rolling clamps over floor

2 men
Bench for men pulling on clamps' top straps

2 men = Pulling on Carbon top Straps

1 - Inspecting bench large —

Rheostat etc Photometer

Bench - Man for putting plat wire
· to Copper ~~Wire~~ - quick running bench
of gas

Small.	Large
300	2100
800	800
500	800
1600	1500
400	500
2000	2500
	5100
	2000
	7100

Bench Screw Mac alongside, clamp machine —

Repair man for pinions —

Carbon House —

Gas house + Generator

Blower

Mercury Clamp. House


April 1875 80 JH
April 1875 80 JH

May 30 74 1880

~~Track + Mules 2281 00~~ and Tax 1 Station

Track 10 Mile 22810 00

Station equipment & 4300 00
2 Side Track

2 Trains
2 Engines 12 Cars 2470 00

29,550 00

Operating Expenses

2 Ton of Coal per day — $14
1 Man with Horses — 5 00
Oil & Repair — 2 50

$21 50

Average 30 Trains a day
of 24 Tons each = 720 Tons.
0.213 cents per Ton per Mile.

Metropolitan Ry. N.Y. of New York 1878

4 Cars in Train weighing 70 tons. on gauge 4'-8½"

curve 90 ft. radius (63°-40')

	Rigid Wheels	Loose Wheels
Resistance on curve per ton	17.00	13.08
" on Straight line "	6.00	4.50
Increased resistance per ton	27.50	21.15
Resistance per ton per degree	0.4319	0.3337





120 Volts

21

60
60

.14
.14

1/3 Ohm Total

1/3 Ohm

50
50
2500

440000
110000
3
330000


















3.
3

150 Tons in 10 hours - about
580 lbs. per min raised 22 ft. high. -
about ½ H.P. -
Bucket. 9 × 23/4 × 37 to hold 10 ft.
allow 60 buckets to empty per min.

Grain bucket 12" c. to c. 18" long 5 5/16" deep 6½" wide
2-6" diam. 22" face crown at bottom
4 ply 20" wide rubber belt. (6 bolts to each bucket)
3 1/4" diam. 22" face crown at top.
Belt speed 450 ft. per min.

4-8" c. to c. 44 buckets 30 revol. per min

Frame of Magnetic Separator. 201

4 - 6" × 10" × 9'-6"
1 - 6" × 10" × 6'
5 - 3" × 3" × 22'-9" ✗
5 - 3" × 3" × 21' - ✗
2 - 3" × 3" × 14' - ✓
6 - 3" × 3" × 8' - ✓
12 - 3" × 3" × 4' -
2 - 3" × 3" × 5' -
2 - 3" × 3" × 6' -
2 - 3" × 3" × 7' - ✓
2 - 3" × 6" × 7'-6" ✓
3 - 3" × 6" × 4' -
2 - 8" × 8" × 12' -
1 - 8" × 8" × 8'-6" -
3 - 8" × 4" × 8'-6"
2 - 8" × 4" × 12'
3 - 8" × 4" × 2'
13 - 2" × 4" × 5'-6"

Lumber 200
Gas house for Lamp factory

8 3 × 4 7'8" long spruce





244

1000

Telephone July 13th 1892 W
J. Kruesi
















264
265










Thomas A. Edison
John F. Randolph
Menlo Park
New Jersey